



BS-1

SIGN:

Trail

COMMENT:

Poor maintenance.
Poor placement.

RECOMMENDATION:

Replace and
reposition sign.



BS-2

SIGN:

No Trespassing

COMMENT:

Ineffective. Access not
limited. Sign poorly
maintained.

RECOMMENDATION:

Replace sign. Limit
access. Increase
patrols of site or
implement other safety
measures.